

Date: Monday, 20/10/2008 3:28:04 PM  
 User: Julie Dawson

## Process Sheet

<b>Customer</b> : CU-DAR001 Dart Helicopters Services	<b>Drawing Name</b> : VERTICAL TUNNEL AFT
<b>Job Number</b> : 42739	
<b>Estimate Number</b> : 13623	
<b>P.O. Number</b> :	<b>Part Number</b> : D38303
<b>This Issue</b> : 20/10/2008 <b>S.O. No.</b> :	<b>Drawing Number</b> : D3830-3
<b>Prsht Rev.</b> : NC	<b>Project Number</b> : IN0002
<b>First Issue</b> : / / <b>Type</b> : R&D THERMOFORMING	<b>Drawing Revision</b> : PROTOTYPE
<b>Previous Run</b> :	<b>Material</b> : Kydex 6185 (TBD)
<b>Written By</b> : <u>Lu</u>	<b>Due Date</b> : 24/10/2008 <b>Qty:</b> 1 <b>Um:</b> Each
<b>Checked &amp; Approved By</b> : <u>Lu</u>	
<b>Comment</b> : Est. Rev. A New Issue 08/10/20 DL	

Additional Product

FOR ENGINEERING USE ONLY

PROTOTYPE

Job Number:



Seq. #:

Machine Or Operation:

Description :

1.0

HAND FINISH TH

HAND FINISHING THERMOFORMING



Comment: HAND FINISHING THERMOFORMING

1) Machine set up

Wk 08.10.21

2.0

HAND FINISH TH

HAND FINISHING THERMOFORMING



Comment: HAND FINISHING THERMOFORMING

1) Cut sheet to required blank size

Wk 08.10.21

(X1)

3.0

THERMOFORMING

THERMOFORMING MACHINE



Comment: THERMOFORMING MACHINE

Thermoform as per Dwg. D3830-3 and folio (FTA 9332 Prototype ) using tool DT 9332

Dwg. Rev. PROTOTYPEFolio Rev. A

Wk 08.10.21

(X1)

4.0

QC2

INSPECT PARTS AS THEY COME OFF MACHINE



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

Visually inspect for proper formation of each part

Wk 08.10.21

(X1)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries

Date: Monday, 20/10/2008 3:28:04 PM  
User: Julie Dawson

## Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: VERTICAL TUNNEL AFT

Job Number: 42739

Part Number: D38303

Job Number:



Seq. #: Machine Or Operation: Description :

5.0

QC8

SECOND CHECK



*BO 08/10/21*



*(X1)*

Comment: SECOND CHECK

6.0

HAND FINISH TH

HAND FINISHING THERMOFORMING



Comment: HAND FINISHING THERMOFORMING

1) Trim to Finished Dimensions

*ML 08.10.21*

*(X1)*

7.0

QC2

INSPECT PARTS AS THEY COME OFF MACHINE



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

Check dimensions to ensure conformity to drawing tolerances.

*PROTOTYPE  
KEEP IN ENG'G LAB*

8.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

**ENGINEERING  
APPROVAL**

9.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location: \_\_\_\_\_

10.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



*00251A*

*Today m2cl  
used per Dmyl*

*EL 07.02.24*

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries